



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

September 15, 1995

TO: Minerals File

FROM: Tony Gallegos, Reclamation Engineer *aa*

RE: Site Inspection, John Welsh, South Shivwits Gypsum Project, S/053/008, Washington County, Utah

Date of Inspection: September 12, 1995
Time of Inspection: 17:45 - 18:45
Conditions: Clear skies, warm
Participants: Tony Gallegos, Tom Munson, DOGM

Purpose of Inspection: To evaluate the status of the site

This inspection was performed while we were in the area. It was not a scheduled inspection. We had difficulty locating the access road to the site. We then found a road that had recently been traveled which lead to an old mine area. The old mine area was evidenced by a number of large timbers and some black waste dump materials. From this location the road continued to a switch back and then up along a ridge to the top. We located an area which was identified in an aerial photo contained in the file.

Disturbances at the area include a small benched area which appears to have been disturbed some time ago. The road is believed to be an existing road. Photographs were taken of this benched area. There seems to be no other major disturbances at this particular claim site. We need to verify that we were at the correct location with a topographic map.

jb
cc: John Welsh, Operator
Larry Gore, BLM Dixie RA
S053008.ins





S/053/008

SHUWITS SOUTH GYPSUM

CORRECT LOCATION?

2000 2000 2000 2000



9/053/008

SHUWITS SOUTH GYPSUM

ACCESS ROAD (BLACK WASTE DUMP MTL)

CORRECT LOCATION?